



WF系列平行轴斜齿减速器

WF SERIES PARALLEL SHAFT GHELICAL GEAR MOTOR




WFAF型 Model WFAF
底脚空心轴安装平行轴斜齿轮减速机
Foot-mounted parallel shaft helical gear
reductor with hollow shaft



WFF型 Model WFF
B5法兰安装平行轴斜齿轮减速机
Parallel shaft helical gear reductor in B5
flange-mounted version




WFAF型 Model WFAF
B5法兰空心轴安装平行轴斜齿轮减速机
Parallel shaft helical gear reductor in B5 flange-mounted
version with hollow shaft




WFAZ 型 Model WFAZ
小法兰空心轴安装平行轴斜齿轮减速机
Short-flange mounted parallel shaft helical gear
reductor with hollow shaft



WF..WR型 Model WF..WR
WF系列与 WR..7系列组合减速机
Combination of WF series reductor and
WR..7 series reductor



WF..S型 Model WF..S
输入轴型，即配输入轴不配电动机的平行轴斜齿轮减速机
Input-shaft style, in another word, parallel shaft helical gear
reductor equipped with input shaft but without the motor



WF型 Model WF
底脚安装平行轴斜齿轮减速机
Foot-mounted parallel shaft helical gear reductor

一、性能特点 Characteristics:

1. 午马减速机是在模块组合体系的基础上设计的, 可以方便地配用各种类型的电动机或采用其它动力输入。同种机型可配用多种功率的电动机。容易实现各种机型之间的组合联接。
2. 传动效率高, 单机型减速机效率高达96%。
3. 传动比划分细, 范围广。组合机型可以形成较大的传动比, 输出转速低。
4. 安装形式多样: 可任意底脚、B5法兰或B14 法兰安装, 底脚安装减速机有两个机加工的底脚安装平面。
1. WUMA reducers are based on the building block design, so it's convenient for them to fit all types of motors or to connect with other power input. The same type of reducers can fit motors with different power, so that it's possible for different types of machines to combine or connect.
2. High transmission efficiency. A single machine can reach a transmission efficiency as much as 96%.
3. Precise division of transmission ratio with a wide range. The combination of machines can produce a larger transmission ratio at a low output rotational speed.
4. Various ways of installation. Horizontal installation at any position or flanged installation, The bottom feet installs the machine that deceleration machine have two bottom feet processes to install the flat surface.

二、场所条件 Working Environment:

1. 环境温度-40℃~50℃。(0℃以下启动时润滑油要加热到0℃以上。)
2. 海拔不超过1000米。
3. 输入转速不大于1800rpm, 齿轮最高圆周速度不超过22m/s。
4. 可用于正反转。
5. 无行业限制。
6. 其他条件下使用请与我公司技术部联系。
1. Working temperature: -40℃~50℃ (The lubrication should be heated until above 0℃ if the machine works Below 0℃.)
2. The working place should be lower than 1,000 meters above sea level.
3. The input rotational speed should not exceed 1,800r/m. The circumferential speed of the gear should not exceed 20m/s.
4. Suitable for normal-reverse rotation.
5. Without industry limitation.
6. Please consult our technical supporting department for other circumstances.

三、选型指南 Instructions for Selection:

在确定使用系数之前必须先确定一天的运行小时数, 每小时的起停次数和负载类型。其中负载类型按下列公式计算:
The daily operating time, the starting frequency and the load classifications be determined before deciding the service factor. The load classifications is calculated with the following formula:

负载类型 Load classification

- I 均匀负载, 惯性加速系数 ≤ 0.2
 - II 中等冲击负载, 惯性加速系数 ≤ 3
 - III 强烈冲击负载, 惯性加速系数 ≤ 10
 - Uniform load, mass acceleration factor ≤ 0.2
 - Medium Impact Load, mass acceleration factor ≤ 3
 - Heavy shock Load, mass acceleration factor ≤ 10
- 如果惯性加速系数 > 10, 请与我公司技术部联系。

$$\text{惯性加速系数} = \frac{\text{所有外部转动惯量}}{\text{驱动电机的转动惯量}}$$

实际的工况系数 f_A 必须满足下式: 使用系数 $f_B \geq$ 工况系数 f_A

使用系数 f_B 已在后面的选型参数表中列出。

允许的轴伸径向载荷及轴向载荷

输出轴端允许的径向载荷及轴向载荷资料, 请与我公司技术部联系。

减速机的使用与维护请参阅随机附带的《减·变速机使用说明书》。

Please contact our technical supporting department in case the mass acceleration factor > 10.

Mass acceleration factor = $\frac{\text{All external mass moments of Inertia}}{\text{Mass moment of inertia on the motor end}}$


The actual operating mode factor (f_A) should meet the following formula: Service factor $f_B \geq$ operating mode factor f_A

The service factor f_B is listed in the parameter selection list.


The permitted overhung loads and the axial forces.

Please contact our technical supporting department for the information on the permitted overhung loads and the axial forces at the output end of the shaft.

Regarding the use and maintenance of the reducer, please refer to the attached Instruction Manual of the Reductor and the Variable Speed Motor.




WF系列结构图:/WFseries structrue drawing:



WF系列平行轴斜齿轮减速器型号规格及机型表示方法:
本系列减速器的型号规格有:WF(37、47、57、67、77、87、97、107、127、157) 等10种, 减速比有4.07~205等多种速比, 可分别配置0.18~132KW。

Type,specification and model notation for WF series parallel shaft bevel gear speed reducers.:
Types,specifications of this series speed reducer have 10 kinds including WF 37、47、57、67、77、87、97、107、127、157 etc, speed reducing ratio:4.07 ~205, which can be allocated to 0.18 ~ 132kW.

五、型号说明 Instructions for Models:



- 注：1.输入轴型没有电动机的各项内容。
 2.无特别说明时Y系列电动机供货按IP54防护等级。
 3.不注明安装形式时，按安装形式图中M1安装形式供货。
 4.不注明接线盒角度时，按安装形式图中0度位置供货。
 5.对输出旋转方向与输入旋转方向有特殊要求的用户，请与我公司技术部联系。
 6.电机尺寸请查看电机外型尺寸表。

- Note:1. The input-shaft style is not equipped with any motor
 2. Motors of Y series are supplied with protection grade of IP54 unless otherwise specified.
 3. The mounting position of M1 as shown in the mounting position example is the default way when supplying unless otherwise specified.
 4. 0° as shown in the mounting position example is the default connection box angle when supplying unless otherwise specified.
 5. Please contact our technical supporting department in case there's any special requirements on the output and input rotatory directions.
 6. About Motor size, please check table of motor's dimensions.

六、电机类型代号 Codes for Motor Types:

Y系列 Y series	Y	防爆电机 Flame-proof Motor	YB	直流电机 Direct Current Motor	Z
制动电机 Brake Motor	YEJ	辊道电机 Roll Motor	YG	变频电机 Variable Frequency Motor	YVP

WF

七、联接法兰L2长度 Length of Connect Flange L2

WF..系列平行轴斜齿轮减速机联接法兰L2长度表

The form on length of the connect flange L2 of the parallel shaft helical gear reductor of WF.. series

电机机座号 Motor frame size 减速机型号 Reductor type	63	71	80	90	100	112	132	160	180	200	225	250	280	315
WF..37	61.5	61.5	80	80	98	—	—	—	—	—	—	—	—	—
WF..47	61.5	61.5	80	80	98	—	—	—	—	—	—	—	—	—
WF..57	56	56	74.5	74.5	90.5	90.5	—	—	—	—	—	—	—	—
WF..67	56	56	74.5	74.5	90.5	90.5	123	—	—	—	—	—	—	—
WF..77	50	50	68.5	68.5	82.5	82.5	111	152.5	—	—	—	—	—	—
WF..87	—	—	63.5	63.5	78.5	78.5	106	147.5	147.5	—	—	—	—	—
WF..97	—	—	—	57.5	72.5	72.5	101	142.5	142.5	144.5	—	—	—	—
WF..107	—	—	—	—	66.5	66.5	95	136.5	136.5	138.5	168.5	—	—	—
WF..127	—	—	—	—	—	—	80	121.5	121.5	123.5	153.5	153.5	153.5	—
WF..157	—	—	—	—	—	—	—	113.5	113.5	115.5	145.5	145.5	145.5	184

八、安装形式图释义 Explanation of mounting position example


	通气孔 Breather valve		油位孔 Oil level plug		放油孔 Oil drain plug
---	-----------------------	---	-----------------------	---	-----------------------

九、选型参数表释义 Explanation of Parameter Selection List

电机功率 Power (kW)	输出转速 Output speed (r/min)	输出转矩 Output torque (N · m)	传动比 Ratio (i)	使用系数 Service factor (fB)	机型号 Type	电机极数 Motor pole	重量 Weight (kg)
0.75	4.5	1603	203.70	0.89	WF 77	6P	99
	4.8	1500	190.60	0.95	WFA 77	6P	110
	5.4	1325	168.40	1.08	WFF 77	6P	96
	6.4	1120	142.30	1.27	WFAF77	6P	102
	7.1	1010	128.30	1.41			

WUMA REDUCER / 午马减速机

WF系列安装方位图/WF series installation direction diagram



WF系列油量表(单位kg) / WF series oil capacity table (Unit:kg)



安装方位 机型号	M1	M2	M3	M4	M5	M6
WF37	1	1.2	0.7	1.2	1	1.1
WF47	1.5	1.8	1.1	1.9	1.5	1.7
WF57	2.5	3.6	2	3.4	2.7	2.8
WF67	2.7	3.8	2.1	3.9	2.9	3.2
WF77	5.1	7.3	4.4	8.2	6.1	6.3
WF87	9.3	12	7.1	12.8	10	10.2
WF97	20.8	25.3	14.2	28.4	20.8	22.5
WF107	26	32	20	39	28	29
WF127	42	56	34	65	46	49
WF157	72	103	65	104	85	80

WF系列重量表 / WF SERIES WEIGHT TABLE



机型号/Type	WF37	WF47	WF57	WF67	WF77	WF87	WF97	WF107	WF127	WF157
重量kg/Weight kg	13	16.5	27	31	55	100	170	260	400	700

注：表中重量为不加油时重量，带输入轴、输入法兰另加10%；带电机根据所配规格另加。
Note: Weight in the table means the weight when oil is not added. When input shaft is furnished, 10% weight should be added; If there is a motor, please add weight according to motor type.



WF/WFAB37-157 安装形式图 WF/WFAB37-157 Mounting position example



WF/WFAT37-157 安装形式图 WF/WFAT37-157 Mounting position example



WFF/WFAF/WFAZ 37-157安装形式图 WFF/WFAF/WFAZ 37-157 Mounting position example



WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
0.12KW						0.12KW							
0.06	15000	22323	0.80	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P	2.5	370	558	1.60	WFA 57WR37 WFAF57WR37 WF 57WR37 WFF 57 WR37	4P		
0.07	12600	19048	0.95			2.7	330	506	1.80				
0.08	10800	16656	1.10			3.0	285	452	2.1				
0.09	9870	14722	1.20			3.2	295	426	2.0				
0.11	7980	12912	1.50			3.6	260	382	2.3				
0.12	7090	11656	1.70			4.2	225	330	2.7				
0.14	6300	10191	1.90			4.6	200	298	3.0				
						5.3	177	262	3.4				
0.09	9590	14767	0.80	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P	2.2	425	622	0.95	WFA 47WR17 WFAF47WR17 WF 47WR17 WFF 47 WR17	4P		
0.12	7610	11348	1.00			2.5	370	543	1.10				
0.14	5890	10039	1.30			2.9	320	475	1.25				
0.16	4880	8548	1.55			3.3	280	419	1.45				
0.18	4740	7674	1.60			2.6	365	524	1.10				
0.20	4120	6767	1.85			2.8	340	489	1.20				
0.23	3530	5954	2.2			3.2	290	427	1.35				
0.26	3070	5223	2.5			3.6	260	381	1.55				
0.30	2890	4567	2.7			4.1	225	334	1.75				
0.39	2140	3521	3.6			4.7	198	295	2.0				
						5.4	166	253	2.4				
0.19	4800	7328	0.90	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P	4.3	210	322	0.95	WFA 37WR17 WFAF37WR17 WF 37WR17 WFF 37 WR17	4P		
0.21	4040	6469	1.05			5.0	184	278	1.10				
0.25	3680	5615	1.15			5.7	157	242	1.30				
0.28	3200	4961	1.35			6.2	149	221	1.35				
0.32	2800	4333	1.55			4.2	225	326	0.90				
0.35	2550	3906	1.70			4.8	195	285	1.05				
0.41	2210	3352	1.95			5.5	170	250	1.20				
0.47	1820	2907	2.4			6.3	150	219	1.35				
0.54	1670	2553	2.6	7.4	127	186	1.60						
					8.3	114	167	1.75					
0.28	3250	4954	0.90	WFA 87WR57 WFAF87WR57 WF 87WR57 WFF 87WR57	4P	3.9	290	228.99	2.8	WFA 67 WFAF67 WF 67 WFF 67	4P		
0.33	2690	4245	1.00			4.6	250	195.39	3.3				
0.37	2200	3721	1.35			5.3	220	170.85	3.8				
0.43	2140	3244	1.40			5.6	205	162.31	4.0				
0.48	1900	2881	1.60			6.3	181	142.40	4.5	WFA 57 WFAF57 WF 57 WFF 57	4P		
0.54	1700	2576	1.75			4.5	255	199.70	2.4				
0.63	1440	2199	2.1			4.9	235	183.60	2.6				
0.72	1240	1930	2.4			5.7	200	157.09	3.0				
0.81	1120	1709	2.7			6.6	173	136.16	3.5				
0.92	980	1493	3.0			7.1	162	127.27	3.7				
1.1	785	1300	3.8			6.9	166	199.70	3.6				
1.2	710	1148	4.2			7.5	153	183.60	3.9				
						8.8	130	157.09	4.6				
				10	113	136.16	5.3						
0.53	1750	2613	0.85	WFA 77WR37 WFAF77WR37 WF 77WR37 WFF 77WR37	4P	4.7	245	190.76	1.65	WFA 47 WFAF47 WF 47 WFF 47	6P		
0.60	1520	2284	1.00			5.1	225	175.38	1.80				
0.68	1340	2029	1.10			6.0	191	150.06	2.1				
0.80	1130	1728	1.35			6.9	166	130.07	2.4				
0.89	1040	1544	1.45			7.4	155	121.57	2.6				
1.0	910	1354	1.65			8.6	134	105.09	3.0				
1.1	810	1200	1.85			10	114	89.29	3.5				
1.3	710	1053	2.1			11	102	79.72	3.9				
1.5	605	910	2.5			7.2	158	190.76	2.5			WFA 47 WFAF47 WF 47 WFF 47	4P
1.7	501	810	2.9			7.9	146	175.38	2.8				
1.9	445	710	3.4			9.2	125	150.06	3.2				
						11	108	130.07	3.7				
0.97	920	1429	0.90	WFA 67WR37 WFAF67WR37 WF 67WR37 WFF 67WR37	4P	7.0	164	128.51	1.20	WFA 37 WFAF37 WF 37 WFF 37	6P		
1.1	830	1271	1.00			7.6	150	117.88	1.35				
1.2	700	1102	1.15			9.0	128	100.36	1.55				
1.4	615	970	1.35			10	110	86.53	1.80				
1.6	540	858	1.50			11	103	80.65	1.95				
1.8	475	755	1.75										
2.2	405	641	2.0										
2.4	375	572	2.2										
2.7	320	509	2.6										
3.2	275	437	3.0										
1.4	655	967	0.90	WFA 57WR37 WFAF57WR37 WF 57WR37 WFF 57 WR37	4P								
1.6	585	851	1.05										
1.9	500	738	1.20										
2.1	435	646	1.40										

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole
0.12KW						0.18KW					
11	107	128.51	1.85			0.46	3160	2881	0.95		
12	98	117.88	2.0			0.51	2820	2576	1.05		
14	83	100.36	2.4			0.60	2400	2199	1.25		
16	72	86.53	2.8			0.68	2080	1930	1.45		
17	67	80.65	3.0			0.77	1860	1709	1.60	WFA 87WR57	4P
20	59	70.50	3.4			0.88	1640	1493	1.85	WFAF87WR57	
21	55	66.09	3.6			1.0	1350	1300	2.2	WF 87WR57	
24	48	58.32	4.1			1.1	1210	1148	2.5	WFF 87WR57	
25	45	54.54	4.4			1.3	1050	1010	2.9		
27	43	51.70	4.7			1.5	940	887	3.2		
29	39	47.02	5.1			1.7	810	780	3.7		
31	36	43.83	5.5								
36	32	38.31	6.3			0.76	1880	1728	0.80		
38	30	35.91	6.7			0.86	1710	1544	0.90		
44	26	31.69	7.6			0.98	1500	1354	1.00		
49	23	28.09	8.6			1.1	1330	1200	1.15	WFA 77WR37	4P
58	20	23.88	10	WFA 37		1.2	1170	1053	1.30	WFAF77WR37	
58	20	23.63	10	WFAF37	4P	1.5	1000	910	1.50	WF 77WR37	
67	17	20.57	12	WF 37		1.6	860	810	1.75	WFF 77WR37	
72	16	19.27	13	WFF 37		1.9	755	710	2.0		
81	14	17.03	14			2.2	670	615	2.2		
87	13	15.81	15								
96	12	14.33	17			1.5	910	858	0.90		
107	11	12.87	19			1.8	800	755	1.00		
125	9.2	11.08	21			2.1	685	641	1.20		
132	8.7	10.42	21			2.3	625	572	1.30		
154	7.4	8.97	24			2.6	540	509	1.50		
186	6.2	7.44	23			3.0	470	437	1.75	WFA 67WR37	4P
205	5.6	6.74	25			3.4	420	384	1.95	WFAF67WR37	
228	5.0	6.05	27			2.6	560	500	1.45	WF 67WR37	
265	4.3	5.21	29			2.9	510	454	1.60	WFF 67WR37	
282	4.1	4.90	29			3.4	440	392	1.85		
327	3.5	4.22	31			4.0	370	333	2.2		
						4.4	325	297	2.5		
						5.1	285	261	2.9		
						5.6	260	238	3.2		
						6.6	215	200	3.8		
0.18KW											
0.10	13500	12912	0.90			2.4	615	558	1.00		
0.11	12100	11656	1.00	WFA 127WR77	4P	2.6	550	506	1.10		
0.13	10700	10191	1.10	WFAF127WR77		2.9	485	452	1.25		
0.15	8980	8831	1.35	WF 127WR77		3.4	415	386	1.45		
0.17	7770	7643	1.55	WFF 127 WR77		3.9	360	338	1.65		
0.20	7150	6715	1.70			3.1	485	426	1.25	WFA 57WR37	4P
0.15	8560	8548	0.90			3.5	430	382	1.40	WFAF57WR37	
0.17	8050	7674	0.95			4.0	370	330	1.60	WF 57WR37	
0.20	7030	6767	1.10	WFA 107WR77	4P	4.4	335	298	1.80	WFF 57 WR37	
0.22	6090	5954	1.25	WFAF107WR77		5.0	295	262	2.0		
0.25	5310	5223	1.45	WF 107WR77		5.8	250	226	2.4		
0.26	4860	4567	1.60	WFF 107 WR77		6.6	215	200	2.8		
0.37	3660	3521	2.1			3.6	400	370	1.00		4P
0.43	2170	3037	2.4			4.1	365	324	1.10		
0.48	2880	3756	2.7			4.6	315	288	1.25		
0.56	2470	2369	3.1			5.3	270	249	1.50	WFA 47WR17	
0.64	2160	2068	3.6			4.0	375	334	1.05	WFAF47WR17	
0.30	4660	4333	0.90			4.5	330	295	1.20	WF 47WR17	
0.34	4260	3906	1.00			5.2	280	253	1.45	WFF 47 WR17	
0.39	3670	3352	1.15			6.1	245	217	1.60		
0.45	3100	2907	1.40	WFA 97WR57	4P	7.0	215	190	1.85		
0.52	2790	2553	1.55	WFAF97WR57		7.4	200	178	2.0		
0.59	2450	2245	1.75	WF 97WR57		7.1	210	186	0.95	WFA 37WR17	4P
0.67	2130	1970	2.0	WFF 97WR57		7.9	188	167	1.05	WFAF37WR17	
0.77	1890	1722	2.3			9.1	166	145	1.20	WF 37WR17	
0.86	1670	1527	2.6			10	146	129	1.35	WFF 37 WR17	
0.99	1380	1327	3.1								
1.1	1280	1171	3.3								

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole				
0.18KW						0.18KW									
3.1	555	281071	2.7	WFA 77	6P	103	17	12.87	12	WFA 37 WFAF37 WF 37 WFF 37	4P				
3.3	520	262.93	2.9	WFAF77		119	14	11.08	13						
3.8	445	225.79	3.4	WF 77		127	14	10.42	14						
				WFF 77		147	12	8.97	15						
3.8	450	228.99	1.80	WFA 67	6P	178	9.7	7.44	15	WFA 37 WFAF37 WF 37 WFF 37	4P				
4.4	385	195.39	2.1	WFAF67		196	8.8	6.74	16						
5.1	340	170.85	2.4	WF 67		218	7.9	6.05	17						
				WFF 67		253	6.8	5.21	18						
						269	6.4	4.90	19						
						313	5.5	4.22	20						
5.8						0.25KW									
6.8	255	195.39	3.2	WFA 67	4P	0.15	13300	8831	0.90	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127WR77	4P				
7.7	225	170.85	3.7	WFAF67		0.17	11500	7643	1.05						
				WF 67		0.19	10400	6715	1.15						
				WFF 67		0.22	9190	5925	1.30						
4.4	395	199.70	1.50	WFA 57 WFAF57 WF 57 WFF 57	6P	0.25	7860	5153	1.55	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107WR77	4P				
4.7	365	183.60	1.65			0.29	6850	4533	1.75						
5.5	310	157.09	1.95			0.22	9000	5954	0.85						
6.4	270	136.16	2.2			0.25	7860	5223	1.00						
6.8	250	127.27	2.4	WFA 57 WFAF57 WF 57 WFF 57	4P	0.28	7090	4567	1.10	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107WR77	4P				
7.9	215	110.01	2.8			0.37	5370	3521	1.45						
6.6	260	199.70	2.3			0.43	4680	3037	1.65						
7.2	240	183.60	2.5			0.47	4240	2756	1.80						
8.4	205	157.09	2.9	WFA 57 WFAF57 WF 57 WFF 57	4P	0.55	3650	2369	2.1	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107WR77	4P				
9.7	177	136.16	3.4			0.63	3180	2068	2.4						
10	166	127.27	3.6			0.81	2440	1597	3.2						
						0.93	2110	1401	3.6						
4.6						0.45									
5.0	345	175.38	1.15	WFA 47	6P	0.51	4050	2553	1.05	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P				
5.8	295	150.06	1.35	WFAF47		0.58	3560	2245	1.20						
6.7	255	130.07	1.55	WF 47		0.66	3100	1970	1.40						
7.2	240	121.57	1.65	WFF 47		0.75	2740	1722	1.55						
6.9	250	190.76	1.60	WFA 47	4P	0.85	2430	1527	1.75	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P				
7.5	230	175.38	1.75	WFAF47		0.98	2040	1327	2.1						
8.8	195	150.06	2.0	WF 47		1.1	1860	1171	2.3						
10	169	130.07	2.4	WFF 47		1.3	1630	1022	2.6						
11	158	121.57	2.5												
7.4						0.67									
8.7	198	100.36	1.00	WFA 37	6P	0.76	2710	1709	1.10	WFA 87WR57 WFAF87WR57 WF 87WR57 WFF 87WR57	4P				
10	171	86.53	1.15	WFAF37		0.87	2380	1493	1.25						
11	159	80.65	1.25	WF 37		1.0	1990	1300	1.50						
12	139	70.50	1.45	WFF 37		1.1	1780	1148	1.70						
						1.3	1550	1010	1.95						
						1.5	1370	887	2.2						
						1.7	1200	780	2.5						
						1.9	1020	674	2.9						
1.2						1.00									
1.4	1450	910	1.05	WFA 77WR37 WFAF77WR37 WF 77WR37 WFF 77WR37	4P	1.6	1260	810	1.20	WFA 77WR37 WFAF77WR37 WF 77WR37 WFF 77WR37	4P				
1.6	1260	810	1.20			1.8	1110	710	1.35						
1.8	1110	710	1.35			2.1	970	615	1.55						
2.1	970	615	1.55			2.4	850	538	1.75						
2.4	850	538	1.75	WFA 37 WFAF37 WF 37 WFF 37	4P	2.7	760	480	2.0	WFA 67WR37 WFAF67WR37 WF 67WR37 WFF 67WR37	4P				
2.7	760	480	2.0			3.2	645	413	2.3						
2.0	1000	641	0.80			3.0	685	437	1.20						
2.3	910	572	0.90			2.6	810	500	1.00						
2.6	795	509	1.05	WFA 67WR37 WFAF67WR37 WF 67WR37 WFF 67WR37	4P	2.9	740	454	1.10	WFA 67WR37 WFAF67WR37 WF 67WR37 WFF 67WR37	4P				
3.0	685	437	1.20			3.3	635	392	1.30						
3.3	635	392	1.30			3.9	535	333	1.55						
3.9	535	333	1.55			4.4	475	297	1.70						
4.4	475	297	1.70	WFA 37 WFAF37 WF 37 WFF 37	4P	5.0	420	261	1.95	WFA 67WR37 WFAF67WR37 WF 67WR37 WFF 67WR37	4P				
5.0	420	261	1.95			5.5	375	238	2.2						
5.5	375	238	2.2												

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole
0.25KW						0.25KW					
3.4	605	386	1.00	WFA 57WR37 WFAF57WR37 WF 57WR37 WFF 57 WR37	4P	11	225	121.57	1.80	WFA 47	4P
3.8	525	338	1.15			12	193	105.09	2.1	WFAF47	
5.1	400	255	1.50			15	164	89.29	2.4	WF 47	
3.4	625	382	0.95							WFF 47	
3.9	535	330	1.10			10	235	128.51	0.85	WFA 37 WFAF37 WF 37 WFF 37	4P
4.4	485	298	1.25			11	215	117.88	0.90		
5.0	425	262	1.40			13	184	100.36	1.10		
5.8	360	226	1.65			15	159	86.53	1.25		
6.5	320	200	1.90			16	148	80.65	1.35		
7.7	270	170	2.2	18	130	70.50	1.55				
5.2	395	249	1.00	WFA 47WR17 WFAF47WR17 WF 47WR17 WFF 47 WR17	4P	20	121	66.09	1.65		
6.0	350	218	1.15			22	107	58.32	1.85		
6.7	305	193	1.30			24	100	54.54	2.0		
7.4	280	175	1.45			25	95	51.70	2.1		
5.1	405	253	1.00			28	86	47.02	2.3		
6.0	355	217	1.10			30	81	43.83	2.5		
6.8	310	190	1.30			34	70	38.31	2.8		
7.3	290	178	1.40			36	66	35.91	3.0		
8.7	240	149	1.65			41	58	31.69	3.4		
9.9	210	131	1.90	46	52	28.09	3.9				
8.9	240	145	0.85	WFA 37WR17 WFAF37WR17 WF 37WR17 WFF 37 WR17	4P	54	44	23.88	4.6		
10	210	129	0.95			55	43	23.63	4.6		
11	193	118	1.05			63	38	20.57	5.3		
13	160	98	1.25			67	35	19.27	5.7		
15	140	87	1.45			76	31	17.03	6.4		
3.1	765	281.71	1.95			82	29	15.81	6.9		
3.3	715	262.93	2.1			91	26	14.33	7.6		
3.9	615	225.79	2.5			101	24	12.87	8.5		
4.4	540	198.31	2.8			117	20	11.08	9.3		
4.7	510	188.40	2.9	125	19	10.42	9.7				
3.8	620	228.99	1.30	WFA 67 WFAF67 WF 67 WFF 67	6P	145	17	8.97	11		
4.5	530	195.39	1.55			175	14	7.44	11		
5.2	465	170.85	1.75			193	12	6.74	11		
5.4	440	162.31	1.85			215	11	6.05	12		
6.2	385	142.40	2.1			249	9.6	5.21	13		
5.7	420	228.99	1.95	WFA 67 WFAF67 WF 67 WFF 67	4P	265	9.0	4.90	13		
6.7	360	195.39	2.3			308	7.7	4.22	14		
7.6	315	170.85	2.6			0.37KW					
8.0	300	162.31	2.8			0.21	14900	6715	0.80	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P
9.1	260	142.40	3.1			0.23	13100	5925	0.90		
4.4	540	199.70	1.10	0.27	11300	5153	1.05				
4.8	500	183.60	1.20	0.30	9850	4533	1.20				
5.6	425	157.09	1.40	0.35	8590	3926	1.40				
5.6	425	157.09	1.40	WFA 57 WFAF57 WF 57 WFF 57	6P	0.40	7510	3454	1.60	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P
6.5	370	136.16	1.60			0.46	6570	3031	1.85		
6.9	345	127.27	1.75			0.45	6720	3037	1.15		
8.0	300	110.01	2.0			0.50	6090	2756	1.25		
6.5	365	199.70	1.65			0.58	5240	2369	1.45		
7.1	335	183.60	1.80	WFA 57 WFAF57 WF 57 WFF 57	4P	0.67	4570	2068	1.70		
8.3	290	157.09	2.1			0.86	3510	1597	2.2		
9.6	250	136.16	2.4			0.61	5070	2245	0.85	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P
10	235	127.27	2.6			0.70	4430	1970	0.95		
12	200	110.01	3.0			0.80	3900	1722	1.10		
5.9	405	150.06	1.00	WFA 47 WFAF47 WF 47 WFF 47	6P	0.90	3460	1527	1.25		
6.8	355	130.07	1.15			1.0	2930	1327	1.45		
7.2	330	121.57	1.20			1.2	2650	1171	1.60		
8.4	285	105.09	1.40			1.4	2310	1022	1.85		
6.8	350	190.76	1.15	WFA 47 WFAF47 WF 47 WFF 47	4P	1.5	1960	898	2.2		
7.4	320	175.38	1.25			1.1	2870	1300	1.05	WFA 87WR57 WFAF87WR57 WF 87WR57 WFF 87WR57	4P
8.7	275	150.06	1.45			1.2	2550	1148	1.20		
10	240	130.07	1.65			1.4	2230	1010	1.35		
				1.6	1970	887	1.50				
						1.8	1720	780	1.75		

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole						
0.37KW						0.37KW											
2.0	1470	674	2.0	WFA 87WR57	4P	5.7	615	157.09	0.95	WFA 57	6P						
2.3	1340	609	2.2	WFAF87WR57		6.6	535	136.16	1.10	WFAF57							
2.7	1130	515	2.7	WF 87WR57		7.1	500	127.27	1.20	WF 57							
3.0	1000	452	3.0	WFF 87WR57		8.2	430	110.01	1.40	WFF 57							
1.7	1810	810	0.85	WFA 77WR37 WFAF77WR37 WF 77WR37 WFF 77WR37	4P	6.9	510	199.70	1.15	WFA 57 WFAF57 WF 57 WFF 57	4P						
1.9	1590	710	0.95			7.5	470	183.60	1.30								
2.2	1390	615	1.10			8.8	400	157.09	1.50								
2.6	1210	538	1.25			10	350	136.16	1.70								
2.9	1080	480	1.40			11	325	127.27	1.85								
3.3	920	413	1.65			13	280	110.01	2.1								
3.8	830	367	1.80			15	240	93.47	2.5								
4.3	730	323	2.0		17	215	83.46	2.8									
3.2	980	437	0.85	WFA 67WR37 WFAF67WR37 WF 67WR37 WFF 67WR37	4P	9.2	385	150.06	1.05	WFA 47 WFAF47 WF 47 WFF 47	4P						
3.6	870	384	0.95			11	335	130.07	1.20								
4.1	770	338	1.05			13	270	105.09	1.50								
4.5	685	305	1.20			15	230	89.29	1.75								
5.4	575	257	1.40			17	205	79.72	1.95								
6.0	510	231	1.60			20	174	68.09	2.3								
5.4	570	255	1.05	WFA 57WR37 WFAF57WR37 WF 57WR37 WFF 57 WR37	4P	21	167	65.36	2.4	WFA 37 WFAF37 WF 37 WFF 37	4P						
6.9	445	201	1.35			16	220	86.53	0.90								
7.6	405	181	1.50			17	205	80.65	0.95								
5.3	605	262	1.00			20	181	70.50	1.10								
6.1	515	226	1.15			21	169	66.09	1.20								
6.9	455	200	1.30			24	149	58.32	1.35								
8.1	385	170	1.55			25	140	54.54	1.45								
9.1	345	152	1.75			27	132	51.70	1.50								
10	300	134	2.0			29	120	47.02	1.65								
						31	112	43.83	1.80								
7.9	395	175	1.00	WFA 47WR17 WFAF47WR17 WF 47WR17 WFF 47 WR17	4P	36	98	38.31	2.0	WFA 37 WFAF37 WF 37 WFF 37	4P						
9.4	335	147	1.20			38	92	35.91	2.2								
11	295	130	1.35			44	81	31.69	2.5								
						49	72	28.09	2.8								
						58	61	23.88	3.3								
2.5	1410	270.68	2.1	WFA 87 WFAF87 WF 87 WFF 87	8P	58	61	23.63	3.3			WFA 37 WFAF37 WF 37 WFF 37	4P				
2.7	1330	255.37	2.3			67	53	20.57	3.8								
3.0	1190	228.93	2.5			72	49	19.27	4.1								
3.5	1020	197.20	2.9			81	44	17.03	4.6								
				WFA 87 WFAF87 WF 87 WFF 87	6P	87	41	15.81	4.9					WFA 37 WFAF37 WF 37 WFF 37	4P		
3.3	1060	270.68	2.8			96	37	14.33	5.4								
3.5	1000	255.37	3.0			107	33	12.87	6.1								
3.9	900	228.93	3.3			125	28	11.08	6.7								
						132	27	10.42	6.9								
4.0	890	225.79	1.70	WFA 77 WFAF77 WF 77 WFF 77	6P	154	23	8.97	7.6	WFA 37 WFAF37 WF 37 WFF 37	4P						
4.5	780	198.31	1.95			186	19	7.44	7.6								
4.8	740	188.40	2.0			205	17	6.74	8.1								
5.4	655	166.47	2.3			228	16	6.05	8.7								
6.3	560	142.27	2.7			265	13	5.21	9.4								
				WFA 77 WFAF77 WF 77 WFF 77	4P	282	13	4.90	9.6			WFA 37 WFAF37 WF 37 WFF 37	4P				
4.9	720	281.71	2.1			327	11	4.22	10								
5.2	675	262.93	2.2			0.55KW								WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P		
6.1	580	225.79	2.6			0.22	20500	6295	0.90								
7.0	510	198.31	3.0			0.25	17400	5404	1.05								
				0.49	8930	2780	2.0										
4.6	765	195.39	1.05	0.56	7760	2427	2.3										
5.3	670	170.85	1.20	0.81	5520	1674	3.3										
5.6	635	162.31	1.30	1.0	4220	1308	4.3										
6.3	560	142.40	1.45	WFA 67 WFAF67 WF 67 WFF 67	6P	1.2	3730	1169	4.8	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P						
7.4	475	120.79	1.75														
6.0	585	228.99	1.40			WFA 67 WFAF67 WF 67 WFF 67	4P	0.35	13300			3926	0.90				
7.1	500	195.39	1.65					0.39	11600			3454	1.05				
8.1	435	170.85	1.85	0.45	10200			3031	1.20								
8.5	415	162.31	1.95														
9.7	365	142.40	2.2														
11	310	120.79	2.7														

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	
0.55KW						0.55KW						
0.57	8100	2369	0.95	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107WR77	4P	9.6	550	142.27	2.7	WFA 77	4P	
0.66	7070	2068	1.10			10	505	130.42	3.0	WFAF77		
0.74	6110	1826	1.25			12	440	114.45	3.4	WF 77		
0.85	5440	1597	1.40			13	420	108.46	3.6	WFF 77		
0.97	4750	1401	1.60			14	365	94.93	4.1			
1.1	4160	1243	1.85			7.0	755	195.39	1.10	WFA 67 WFAF67 WF 67 WFF 67	4P	
1.2	3700	1087	2.1			8.0	660	170.85	1.25			
1.4	3180	950	2.4			8.4	625	162.31	1.30			
1.6	2770	834	2.8			9.6	550	142.40	1.50			
2.1	2150	640	3.6	11	465	120.79	1.75					
				12	420	109.04	1.95					
				14	370	95.94	2.2					
				15	350	90.59	2.3					
				17	310	79.76	2.7					
1.0	4530	1327	0.95	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P	8.7	605	157.09	1.00	WFA 57 WFAF57 WF 57 WFF 57	4P	
1.2	4060	1171	1.05			10	525	136.16	1.15			
1.3	3550	1022	1.20			11	490	127.27	1.20			
1.5	3050	898	1.40			12	425	110.01	1.40			
1.7	2690	784	1.60			15	360	93.47	1.65			
2.0	2340	690	1.85			16	320	83.46	1.85			
2.2	2060	605	2.1			19	280	72.98	2.1			
2.6	1790	529	2.4			20	265	68.22	2.3			
2.9	1580	467	2.7			23	230	58.97	2.6			
3.4	1360	406	3.2	WFA 87WR57 WFAF87WR57 WF 87WR57 WFF 87WR57	4P	13	405	105.09	1.00	WFA 47 WFAF47 WF 47 WFF 47	4P	
3.7	1220	363	3.5			15	345	89.29	1.15			
						17	310	79.72	1.30			
						20	265	68.09	1.50			
						21	250	65.36	1.60			
						24	220	56.49	1.85			
						28	185	48.00	2.2			
						32	166	42.86	2.4			
						23	225	58.32	0.90	WFA 37 WFAF37 WF 37 WFF 37	4P	
				25	210	54.54	0.95					
				26	200	51.70	1.00					
				29	182	47.02	1.10					
				31	169	43.83	1.20					
				36	148	38.31	1.35					
				38	139	35.91	1.45					
				43	122	31.69	1.65					
				48	109	28.09	1.85					
				57	92	23.68	2.2					
				58	91	23.63	2.2					
				66	79	20.57	2.5					
				71	74	19.27	2.7					
				80	66	17.03	3.0					
				95	55	14.33	3.6					
				106	50	12.87	4.0					
				123	43	11.08	4.4					
				130	40	10.42	4.6					
				152	35	8.97	5.1					
				170	31	8.01	5.5					
				183	29	7.44	5.1					
				202	26	6.74	5.4					
				225	23	6.05	5.8					
				261	20	5.21	6.2					
				277	19	4.90	6.3					
				322	16	4.22	6.8					
				361	15	3.77	7.2					
0.55KW						0.75KW						
0.50	12300	2780	1.45	WFA 157WR97	4P	0.57	10700	2427	1.70	WFAF157WR97	4P	
0.57	10700	2427	1.70	WFAF157WR97		0.82	7580	1674	2.4	WF 157WR97		
0.82	7580	1674	2.4	WF 157WR97		1.1	5830	1308	3.1	WFF 157WR97		
1.1	5830	1308	3.1	WFF 157WR97		1.2	5170	1169	3.5			
1.2	5170	1169	3.5									

WF

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
0.75KW						0.75KW							
0.46	13800	3031	0.85	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P	6.1	1170	225.79	1.30	WFA 77 WFAF77 WF 77 WFF 77	4P		
0.52	12400	2672	0.95			7.0	1030	198.31	1.45				
0.59	10900	2357	1.10			7.3	980	188.40	1.55				
0.68	9390	2038	1.30			8.3	860	166.47	1.75				
0.77	8190	1784	1.45			9.7	740	142.27	2.0				
0.86	7350	1606	1.65			11	675	130.42	2.2				
						12	595	114.45	2.5				
						13	565	108.46	2.7				
0.76						8.1	890	170.85	0.90	WFA 67 WFAF67 WF 67 WFF 67	4P		
0.86	7400	1597	1.05	8.5	840	162.31	0.95						
0.98	6470	1401	1.20	9.7	740	142.40	1.10						
1.1	5690	1243	1.35	11	625	120.79	1.30						
1.3	5040	1087	1.50	13	565	109.04	1.45						
1.5	4350	950	1.75	14	500	95.94	1.65						
1.7	3800	834	2.0	15	470	90.59	1.75						
2.2	2940	640	2.6	17	415	79.76	2.0						
3.2	2000	436	3.8	20	350	67.65	2.3						
						23	315	61.07	2.6				
1.4						11	660	127.27	0.90	WFA 57 WFAF57 WF 57 WFF 57	4P		
1.5	4150	898	1.05	13	570	110.01	1.05						
1.8	3660	784	1.20	15	485	93.47	1.25						
2.0	3190	690	1.35	17	435	83.46	1.40						
2.3	2800	605	1.55	19	380	72.98	1.60						
2.6	2440	529	1.75	20	355	68.22	1.70						
3.0	2160	467	2.0	23	305	58.97	1.95						
3.4	1860	406	2.3	28	260	50.10	2.3						
3.8	1670	363	2.6	31	230	44.73	2.6						
2.0						17	415	79.72	0.95	WFA 47 WFAF47 WF 47 WFF 47	4P		
2.3	2830	609	1.05	20	355	68.09	1.15						
2.7	2390	515	1.25	21	340	65.36	1.20						
3.0	2100	452	1.45	24	295	56.49	1.35						
4.0	1590	345	1.90	29	250	48.00	1.60						
				32	220	42.86	1.80						
3.8						38	190	36.61	2.1	WFA 37 WFAF37 WF 37 WFF 37	4P		
4.3	1520	323	1.00	40	178	34.29	2.2						
4.9	1310	280	1.15	48	150	28.88	2.7						
2.7						29	145	47.02	0.80			WFA 37 WFAF37 WF 37 WFF 37	4P
	2640	254.40	2.9	31	230	43.83	0.90						
				36	199	38.31	1.00						
2.5						38	186	35.91	1.05	WFA 37 WFAF37 WF 37 WFF 37	4P		
2.7	2630	263.41	1.65	44	165	31.69	1.20						
3.1	2320	223.88	1.85	49	146	28.09	1.35						
				58	124	23.88	1.60						
3.2						58	123	23.63	1.65			WFA 37 WFAF37 WF 37 WFF 37	4P
3.5	2020	253.41	2.1	67	107	20.57	1.85						
4.0	1780	223.88	2.4	72	100	19.27	2.0						
				81	88	17.03	2.3						
3.3						96	74	14.33	2.7	WFA 37 WFAF37 WF 37 WFF 37	4P		
3.5	2150	270.68	1.40	107	67	12.87	3.0						
3.9	1820	228.93	1.65	125	58	11.08	3.3						
4.6	1570	197.20	1.90	132	54	10.42	3.4						
5.0	1430	179.97	2.1	154	47	8.97	3.8						
5.6	1270	159.61	2.4	205	35	6.74	4.0						
5.1						228	31	6.05	4.3	WFA 37 WFAF37 WF 37 WFF 37	4P		
5.4	1400	270.68	2.1	265	27	5.21	4.6						
	1330	255.37	2.3	282	25	4.90	4.7						
	1190	228.93	2.5	327	22	4.22	5.0						
5.4						366	20	3.77	5.4			WFA 37 WFAF37 WF 37 WFF 37	4P
4.8	1500	188.40	1.00	1.1KW				0.50	18200				
5.4	1320	166.47	1.15	0.58	16000	2427	1.15	WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P				
6.3	1130	142.27	1.30	0.64	14300	2185	1.25						
6.9	1040	130.42	1.45	0.72	12700	1944	1.40						
				0.84	11200	1674	1.60						

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
1.1KW						1.1KW							
1.1	8640	1308	2.1	WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P	11	980	130.42	1.55	WFA 77 WFAF77 WF 77 WFF 77	4P		
1.2	7680	1169	2.3			12	850	114.45	1.75				
1.5	6190	953	2.9			13	810	108.46	1.85				
1.7	5450	845	3.3			15	710	94.93	2.1				
3.1	2880	446	6.2			16	640	85.52	2.3				
4.6	1950	302	9.2			19	565	75.02	2.7				
0.69	13800	2038	0.85	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P	12	910	120.79	0.90	WFA 67 WFAF67 WF 67 WFF 67	4P		
0.79	12000	1784	1.00			13	820	109.04	1.00				
0.87	10800	1606	1.10			15	720	95.94	1.15				
1.0	9350	1390	1.30			15	680	90.59	1.20				
1.1	8170	1220	1.45			18	600	79.76	1.35				
1.3	7260	1077	1.65			21	510	67.65	1.60				
1.1	8360	1243	0.90	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P	23	460	61.07	1.80	WFA 67 WFAF67 WF 67 WFF 67	4P		
1.3	7370	1087	1.05			26	105	53.73	2.0				
1.5	6390	950	1.20			28	380	50.74	2.2				
1.7	5590	823	1.35			32	325	43.20	2.5				
1.9	4910	723	1.55			36	395	39.23	2.7				
2.2	4310	640	1.80			41	255	34.01	2.9				
2.0	4670	690	0.90	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P	17	625	83.46	0.95	WFA 57 WFAF57 WF 57 WFF 57	4P		
2.3	4100	605	1.05			19	550	72.98	1.10				
2.7	3580	529	1.20			21	510	68.22	1.15				
3.0	3160	467	1.35			24	440	58.97	1.35				
3.5	2730	406	1.55			28	375	50.10	1.60				
3.8	2450	363	1.75			31	335	44.73	1.80				
3.1	3070	452	1.00	WFA 87WR57 WFAF87WR57 WF 87WR57 WFF 87WR57	4P	37	285	38.21	2.1	WFA 57 WFAF57 WF 57 WFF 57	4P		
4.1	2330	345	1.30			39	270	35.79	2.2				
4.7	2020	300	1.50			46	225	30.15	2.6				
5.6	1670	249	1.80			25	425	56.49	0.95				
2.7	3930	254.40	1.95	WFA 107 WFAF107 WF 107 WFF 107	8P	29	360	48.00	1.10	WFA 47 WFAF47 WF 47 WFF 47	4P		
3.2	3330	215.37	2.3			33	320	42.86	1.25				
3.4	3080	199.31	2.5			38	275	36.61	1.45				
3.8	2760	178.64	2.8			41	255	34.29	1.55				
3.3	3160	276.77	1.35	WFA 97 WFAF97 WF 97 WFF 97	6P	48	215	28.88	1.85	WFA 37 WFAF37 WF 37 WFF 37	4P		
3.6	2890	253.41	1.50			45	230	30.86	1.75				
4.1	2560	223.88	1.70			48	220	29.32	1.80				
4.8	2170	189.92	2.0			54	193	25.72	2.1				
5.3	2000	174.87	2.2	WFA 97 WFAF97 WF 97 WFF 97	4P	64	164	21.82	2.4	WFA 37 WFAF37 WF 37 WFF 37	4P		
5.1	2080	276.77	2.1			71	148	19.70	2.7				
5.5	1900	253.41	2.3			44	240	31.69	0.85				
6.2	1680	223.88	2.6			50	210	28.09	0.95				
3.4	3090	270.68	0.95	WFA 87 WFAF87 WF 87 WFF 87	6P	59	179	23.88	1.10	WFA 37 WFAF37 WF 37 WFF 37	4P		
3.6	2920	255.37	1.05			68	154	20.57	1.30				
4.0	2610	228.93	1.15			73	145	19.27	1.40				
4.7	2250	197.20	1.35			82	128	17.03	1.55				
5.1	2050	179.97	1.45			98	108	14.33	1.85				
5.8	1820	159.61	1.65			109	97	12.87	2.1				
5.2	2030	270.68	1.50	WFA 87 WFAF87 WF 87 WFF 87	4P	126	83	11.08	2.3	WFA 37 WFAF37 WF 37 WFF 37	4P		
5.5	1920	255.37	1.55			134	78	10.42	2.4				
6.1	1720	228.93	1.75			156	67	8.97	2.6				
7.1	1480	197.20	2.0			175	60	8.01	2.8				
7.8	1350	179.97	2.2			208	51	6.74	2.8				
8.8	1200	159.61	2.5			231	45	6.05	3.0				
10	1010	134.16	3.0	WFA 87 WFAF87 WF 87 WFF 87	4P	269	39	5.21	3.2	WFA 37 WFAF37 WF 37 WFF 37	4P		
11	930	123.29	3.2			286	37	4.90	3.3				
7.1	1490	198.31	1.00			332	32	4.22	3.5				
7.4	1410	188.40	1.05			372	28	3.77	3.7				
8.4	1250	166.47	1.20			1.5KW							
9.8	1070	142.27	1.40			0.58	21900	2427	0.80			WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P
				0.65	19700	2185	0.90						
				0.73	17500	1944	1.05						
				0.84	15300	1674	1.20						
				1.1	11900	1308	1.50						
				1.2	10600	1169	1.70						

WF

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole
1.5KW						1.5KW					
1.5	8540	953	2.1	WFA 157WR97	4P	13	1100	108.46	1.35	WFA 77 WFAF77 WF 77 WFF 77	4P
1.7	7530	845	2.4	WFAF157WR97		15	960	94.93	1.55		
3.2	3980	446	4.5	WF 157WR97		16	870	85.52	1.75		
4.7	2690	302	6.7	WFF 157 WR97		19	760	75.02	1.95		
0.88	14800	1606	0.80	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P	19	735	72.50	2.0	WFA 77 WFAF77 WF 77 WFF 77	4P
1.0	12800	1390	0.95			21	675	66.46	2.2		
1.2	11200	1220	1.05			24	595	58.32	2.5		
1.3	9910	1077	1.20			26	560	55.27	2.7		
1.5	8520	930	1.40			29	490	48.37	3.0		
1.7	7500	820	1.60			32	445	43.58	3.4		
1.9	6630	727	1.80			37	390	38.23	3.9		
2.2	5960	648	2.0			39	370	36.58	3.0		
1.5	8730	950	0.90	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P	45	320	31.51	4.3	WFA 67 WFAF67 WF 67 WFF 67	4P
1.7	7640	834	1.00			16	920	90.59	0.90		
1.9	6730	736	1.15			18	810	79.76	1.00		
2.2	5890	640	1.30			21	685	67.65	1.20		
2.5	5110	560	1.50			23	620	61.07	1.30		
2.9	4460	489	1.70			26	545	53.73	1.50		
3.2	4010	436	1.90			28	515	50.74	1.60		
3.8	3400	370	2.3			33	440	43.20	1.85		
2.7	4880	529	0.90	WFA 97WR57 WFAF97WR57 WF 97WR57 WFF 97WR57	4P	36	400	39.26	1.95	WFA 67 WFAF67 WF 67 WFF 67	4P
3.0	4310	467	1.00			39	370	36.30	2.2		
3.5	3730	406	1.15			44	325	32.08	2.5		
3.9	3340	363	1.30			51	280	27.41	2.9		
4.1	3180	345	0.95	WFA 87WR57 WFAF87WR57 WF 87WR57 WFF 87WR57	4P	56	255	25.13	3.2	WFA 57 WFAF57 WF 57 WFF 57	4P
4.7	2760	300	1.10			24	600	58.97	1.00		
5.7	2290	249	1.30			28	510	50.10	1.20		
2.8	5210	254.40	1.50			32	455	44.73	1.30		
3.2	4410	215.37	1.75	WFA 107 WFAF107 WF 107 WFF 107	8P	37	390	39.21	1.55	WFA 57 WFAF57 WF 57 WFF 57	4P
3.5	4080	199.31	1.90			39	365	35.79	1.65		
3.9	3660	178.64	2.1			47	305	30.15	1.95		
3.6	3960	254.40	1.95			33	435	42.86	0.90	WFA 47 WFAF47 WF 47 WFF 47	4P
4.3	3350	215.37	2.3	WFA 107 WFAF107 WF 107 WFF 107	6P	39	370	36.61	1.10		
4.6	3100	199.31	2.5			41	350	34.29	1.15		
5.2	2780	178.64	2.8			49	295	28.88	1.35		
3.3	4310	276.77	1.00	WFA 97 WFAF97 WF 97 WFF 97	6P	46	315	30.86	1.30	WFA 47 WFAF47 WF 47 WFF 47	4P
3.6	3950	253.41	1.10			48	300	29.32	1.35		
4.1	3490	223.88	1.25			55	260	25.72	1.55		
4.8	2960	189.92	1.45			65	220	21.82	1.80		
5.3	2720	174.87	1.60	WFA 97 WFAF97 WF 97 WFF 97	4P	72	200	19.70	2.0	WFA 37 WFAF37 WF 37 WFF 37	4P
5.1	2810	276.77	1.55			81	176	17.33	2.3		
5.6	2570	253.41	1.65			86	166	16.36	2.4		
6.3	2270	223.88	1.90			101	142	13.93	2.8		
7.4	1930	189.92	2.2	WFA 87 WFAF87 WF 87 WFF 87	4P	69	210	20.57	0.95	WFA 37 WFAF37 WF 37 WFF 37	4P
8.1	1780	174.87	2.4			73	196	19.27	1.00		
5.2	2750	270.68	1.10			83	173	17.03	1.15		
5.5	2590	255.37	1.15			98	146	14.33	1.35		
6.2	2330	228.93	1.30	WFA 87 WFAF87 WF 87 WFF 87	4P	110	131	12.87	1.55	WFA 37 WFAF37 WF 37 WFF 37	4P
7.2	2000	197.20	1.50			127	113	11.08	1.70		
7.8	1830	179.97	1.65			135	106	10.42	1.75		
8.8	1620	159.61	1.85			157	91	8.97	1.90		
11	1360	134.16	2.2	WFA 77 WFAF77 WF 77 WFF 77	4P	176	81	8.01	2.1	WFA 37 WFAF37 WF 37 WFF 37	4P
13	1110	109.49	2.7			209	69	6.74	2.0		
14	990	97.89	3.0			233	62	6.05	2.2		
8.5	1690	166.47	0.90			271	53	5.21	2.4		
9.9	1450	142.27	1.05	WFA 77 WFAF77 WF 77 WFF 77	4P	288	50	4.90	2.4	WFA 37 WFAF37 WF 37 WFF 37	4P
11	1320	130.42	1.15			334	43	4.22	2.6		
12	1160	114.45	1.30			374	38	3.77	2.7		

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole			
2.2KW						2.2KW								
0.98	18900	1441	0.95	WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P	11	1840	123.29	1.65	WFA 87 WFAF87 WF 87 WFF 87	4P			
1.1	17600	1308	1.00			13	1630	109.49	1.85					
1.2	15700	1169	1.15			14	1460	97.89	2.1					
1.5	12700	953	1.40			16	1310	88.01	2.3					
1.7	11200	845	1.60			18	1140	76.39	2.6					
1.9	10100	764	1.80			21	1020	68.40	2.9					
2.1	9020	680	2.0			25	850	56.75	3.5					
2.5	7610	576	2.4			28	750	50.36	3.9					
3.2	5940	446	3.0			31	675	45.28	4.2					
4.7	4020	302	4.5											
5.2	3630	273	5.0	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P	12	1710	114.45	0.90	WFA 77 WFAF77 WF 77 WFF 77	4P			
6.1	3060	232	5.9			13	1620	108.46	0.95					
7.2	2590	197	6.9			15	1410	94.93	1.05					
						16	1270	85.52	1.20					
1.3	14600	1077	0.80			19	1120	75.02	1.35					
1.5	12600	930	0.95			21	990	66.46	1.50					
1.7	11100	820	1.10			24	870	58.32	1.75					
1.9	9830	727	1.20			26	820	55.27	1.80					
2.2	8810	648	1.35			29	720	48.37	2.1					
2.6	7460	549	1.60			32	650	43.58	2.3					
2.8	6720	495	1.80	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P	39	545	36.58	2.0	WFA 67 WFAF67 WF 67 WFF 67	4P			
3.3	5810	428	2.1			45	470	31.51	2.9					
						49	430	28.75	3.3					
2.2	8700	640	1.90			55	380	25.50	4.0					
2.5	7580	560	1.00											
2.9	6610	489	1.15			23	910	61.07	0.90	WFA 57 WFAF57 WF 57 WFF 57	4P			
3.2	5930	436	1.30			26	800	53.73	1.00					
3.8	5030	370	1.55			28	755	50.74	1.10					
4.2	4520	333	1.70			33	645	43.20	1.25					
						36	585	39.26	1.35					
3.9	4940	363	0.85			41	505	34.01	1.45					
4.9	3890	285	1.10			44	480	32.08	1.70					
5.8	3340	245	1.30			51	410	27.41	2.0					
						56	375	25.13	2.2					
2.8	7640	254.40	1.00			64	330	22.05	2.5					
3.2	6460	215.37	1.20	67	310	20.90	2.6	WFA 47 WFAF47 WF 47 WFF 47	4P					
3.5	5980	199.31	1.30	77	275	18.29	3.0							
3.9	5360	178.64	1.45											
3.7	5690	254.40	1.35	32	665	44.73	0.90							
4.4	4810	215.37	1.60	37	570	38.21	1.05							
4.7	4450	199.31	1.70	39	535	35.79	1.15							
5.3	3990	178.64	1.90	47	450	30.15	1.30							
						56	370			24.96	1.55			
5.5	3790	254.40	2.0	67	315	21.17	1.90							
6.6	3210	215.37	2.4	74	285	19.11	2.1							
7.1	2970	199.31	2.6	84	250	16.81	2.4							
7.9	2660	178.64	2.9	89	235	15.88	2.5							
4.2	5000	223.88	0.85	WFA 97	6P	55	385	25.72	1.05	WFA 47 WFAF47 WF 47 WFF 47	4P			
5.9	4240	189.92	1.00	WFAF97		65	328	21.82	1.25					
5.4	3910	174.87	1.10	WF 97		72	295	19.70	1.35					
6.0	3490	156.30	1.25	WFF 97		81	260	17.33	1.55					
						86	245	16.36	1.65					
5.1	4120	276.77	1.05	WFA 97 WFAF97 WF 97 WFF 97	4P	101	210	13.93	1.95	WFA 37 WFAF37 WF 37 WFF 37	4P			
5.6	3780	253.41	1.15			111	189	12.66	2.1					
6.3	3340	223.88	1.30			129	163	10.97	2.5					
7.4	2830	189.92	1.50			157	133	8.96	2.5					
8.1	2610	174.87	1.65											
9.0	2330	156.30	1.85			98	245	14.33	0.95					
10	2100	140.71	2.0			110	192	12.87	1.05					
11	1900	127.42	2.3			127	165	11.08	1.15					
						135	155	10.42	1.20					
7.2	2940	197.20	1.00	WFA 87	4P	157	134	8.97	1.30					
7.8	2680	179.97	1.10	WFAF87		176	119	8.01	1.40					
8.8	2380	159.61	1.25	WF 87		209	100	6.74	1.40					
11	2000	134.16	1.50	WFF 87		233	90	6.05	1.50					
						271	78	5.21	1.60					
						288	73	4.90	1.65					
						334	63	4.22	1.75					
						374	56	3.77	1.85					

WUMA REDUCER /

午马减速机

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
3.0KW						3.0KW							
1.2	21700	1169	0.85	WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P	32	880	43.20	0.95	WFA 67 WFAF67 WF 67 WFF 67	4P		
1.5	17600	953	1.00			36	800	39.26	0.95				
1.7	15600	845	1.15			41	695	34.01	1.05				
1.8	14100	764	1.30			44	655	32.08	1.25				
2.1	12500	680	1.45			51	560	27.41	1.45				
2.4	10600	576	1.70			56	515	25.13	1.60				
3.1	8250	446	2.2			63	450	22.05	1.80				
4.6	5580	302	3.2			67	430	20.90	1.90				
5.1	5040	273	3.6			77	375	18.29	2.2				
6.1	4250	232	4.2			85	335	16.48	2.4				
7.1	3610	197	5.0	97		295	14.46	2.8					
1.9	13600	727	0.90	WFA 127WR77	4P	56	510	24.96	1.15	WFA 57 WFAF57 WF 57 WFF 57	4P		
2.2	12200	648	1.00	WFAF127WR77		66	435	21.17	1.40				
2.5	10300	549	1.15	WF 127WR77		73	390	19.11	1.55				
2.8	9270	495	1.30	WFF 127 WR77		83	345	16.81	1.75				
3.2	8170	436	0.95	WFA 107WR77	88	325	15.88	1.75	WFA 47 WFAF47 WF 47 WFF 47			4P	
3.8	6930	370	1.10	WFAF107WR77	104	275	13.52	2.2					
4.2	6240	333	1.25	WF 107WR77	114	250	12.29	2.4					
4.8	5460	291	1.40	WFF 107 WR77	132	220	10.64	2.8					
3.7	7750	254.40	1.00	WFA 107	6P	71	405	19.70	1.00	WFA 37 WFAF37 WF 37 WFF 37	4P		
4.4	6560	215.37	1.15	WFAF107		81	355	17.33	1.15				
4.7	6070	199.31	1.25	WF 107		86	335	16.36	1.20				
5.3	5440	178.64	1.40	WFF 107		100	285	13.93	1.40				
5.5	5210	254.40	1.50	WFA 107 WFAF107 WF 107 WFF 107	4P	111	260	12.66	1.55			WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P
6.5	4410	215.37	1.75			128	225	10.97	1.80				
7.0	4080	199.31	1.90			156	183	8.96	1.80				
7.8	3660	178.64	2.1			126	225	11.08	0.85				
8.7	3300	161.28	2.3	134		215	10.42	0.85					
6.2	4580	233.88	0.95	WFA 97 WFAF97 WF 97 WFF 97	4P	156	184	8.97	0.95	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127 WR77	4P		
7.4	3890	189.92	1.10			175	164	8.01	1.05				
8.0	3580	174.87	1.20			208	138	6.74	1.00				
9.0	3200	156.30	1.35			231	124	6.05	1.10				
9.9	2880	140.71	1.50			269	107	5.21	1.15				
11	2610	127.42	1.65			286	100	4.90	1.20				
12	2310	112.99	1.85			332	86	4.22	1.25				
14	2090	102.16	2.1			372	77	3.77	1.35				
16	1840	89.85	2.3	4.0KW									
10	2750	134.16	1.10	WFA 87 WFAF87 WF 87 WFF 87	4P	1.7	20600	845	0.85			WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P
11	2520	123.29	1.20			1.9	18600	764	0.95				
13	2240	109.49	1.35			2.1	16600	680	1.10				
14	2000	97.89	1.50			2.5	14000	576	1.30				
16	1800	88.01	1.65			3.2	10900	446	1.65				
18	1560	76.39	1.90			4.7	7390	302	2.4				
20	1400	68.40	2.1			5.2	6670	273	2.7				
25	1160	56.75	2.6			6.1	5640	232	3.2				
28	1030	50.36	2.8			7.2	4780	197	3.8				
16	1750	85.52	0.85	WFA 77 WFAF77 WF 77 WFF 77	4P	2.6	13600	549	0.90	WFA 127 WFAF127 WF 127 WFF 127	4P		
19	1540	75.02	1.00			2.9	12200	495	1.00				
21	1360	66.46	1.10			3.3	10600	428	1.15				
24	1190	58.32	1.25			3.8	9270	376	1.30	WFA 107WR77 WFAF107WR77 WF 107WR77 WFF 107 WR77	4P		
25	1130	55.27	1.35			4.3	8230	333	1.95				
29	990	48.37	1.50			4.9	7190	291	1.05				
32	890	43.58	1.70			5.6	6310	255	1.20	WFA 127 WFAF127 WF 127 WFF 127	4P		
37	780	38.23	1.90			4.2	9060	170.83	1.30				
38	750	36.58	1.50			4.7	8150	153.67	1.45				
44	645	31.51	2.1			5.7	6650	125.37	1.80				
49	590	28.75	2.4										
55	520	25.50	2.9										
65	440	21.43	3.4										

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole
4.0KW						4.0KW					
5.6	6840	254.40	1.10	WFA 107 WFAF107 WF 107 WFF 107	4P	67	570	21.17	1.05	WFA 57 WFAF57 WF 57 WFF 57	4P
6.6	5790	215.37	1.35			74	515	19.11	1.15		
7.1	5360	199.31	1.45			84	450	16.81	1.35		
7.9	4810	178.64	1.60			89	425	15.88	1.40		
8.8	4340	161.28	1.75			105	365	13.52	1.65		
9.7	3940	146.49	1.95			116	330	12.29	1.80		
11	3500	129.97	2.2			133	285	10.64	2.1		
12	3170	117.94	2.4			153	250	9.31	1.70		
14	2730	101.38	2.8	173	220	8.19	1.90	5.5KW	WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157WR97	4P	
8.1	4700	174.87	0.90	184	210	7.73	2.0				
9.1	4200	156.30	1.00	216	177	6.58	2.4				
10	3780	140.71	1.15	237	161	5.98	2.6				
11	3430	127.42	1.25	274	139	5.18	3.0				
13	3040	112.99	1.40	2.5	19300	576	0.95				
14	2750	102.16	1.55	2.8	16800	503	1.05				
15	2620	97.58	1.65	3.2	15000	446	1.20				
16	2420	89.85	1.80	4.1	11800	353	1.55	WFA 127WR77 WFAF127WR77 WF 127WR77 WFF 127WR77	4P		
18	2160	80.31	2.0	4.7	10100	302	1.80				
20	1940	72.30	2.2	5.2	9160	273	1.95				
22	1760	65.47	2.4	6.2	7750	232	2.3				
13	2950	109.49	1.00	7.1	6750	202	2.7				
15	2630	97.89	1.15	7.3	6570	197	2.7				
16	2370	88.01	1.25	3.4	14000	418	0.85				
19	2050	76.39	1.45	3.8	12600	374	0.95				
21	1840	68.40	1.65	4.6	10500	312	1.15	WFA 157 WFAF157 WF 157 WFF 157	8P		
25	1530	56.75	1.95	4.9	9840	293	1.20				
28	1350	50.36	2.2	5.5	8680	259	1.40				
31	1220	45.28	2.3	6.4	7500	223	1.60				
21	1790	66.46	0.85	WFA 77 WFAF77 WF 77 WFF 77	4P	3.3	14500			428	0.85
24	1570	58.32	0.95			3.8	12700			376	0.95
26	1490	55.27	1.00			2.7	19800			267.43	0.90
29	1300	48.37	1.15			3.3	16100			217.62	1.10
33	1170	43.58	1.30			4.0	13200	178.20	1.35		
37	1030	38.23	1.45			4.4	12100	162.96	1.50		
42	910	33.74	1.65			5.0	10500	141.80	1.70		
47	800	29.91	1.85			5.7	9260	125.14	1.95		
56	685	25.54	2.1			6.5	8030	108.49	2.2		
45	850	31.51	1.65	7.4	7140	96.53	2.5	WFA 127 WFAF127 WF 127 WFF 127	8P		
49	775	28.75	1.85	8.4	6350	85.80	2.8				
56	685	25.50	2.2	9.1	5800	78.46	3.1				
66	575	21.43	2.6	10	5050	68.28	3.6				
72	530	19.70	2.8	4.2	12600	170.38	0.95				
52	735	27.41	1.10	4.6	11400	153.27	1.05				
57	675	25.13	1.20	5.7	9270	125.04	1.30				
64	595	22.05	1.40	6.2	8460	114.04	1.40				
68	560	20.90	1.45	6.6	7910	215.37	0.95			WFA 107 WFAF107 WF 107 WFF 107	4P
78	490	18.29	1.64	7.2	7320	199.31	1.05				
86	445	16.48	1.85	8.0	6560	178.64	1.15				
98	390	14.46	2.1	8.9	5920	161.28	1.30				
111	345	12.76	2.4	9.8	5380	146.49	1.45				
126	305	11.31	2.7	11	4770	129.97	1.60				
147	260	9.66	3.2	12	4330	117.94	1.75				
156	245	9.08	2.2	14	3720	101.38	2.1				
165	230	8.60	2.5	15	3400	92.47	2.3				
189	205	7.53	3.0	16	3250	88.49	2.4	WFA 97 WFAF97 WF 97 WFF 97	4P		
209	183	6.78	3.4	17	3080	83.99	2.5				
239	160	5.95	3.8	11	4680	127.42	0.90				
270	141	5.25	4.2	13	4150	112.99	1.05				
305	125	4.66	4.5	14	3750	102.16	1.15				
357	107	3.97	4.7								

WUMA REDUCER /

午马减速机

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
5.5KW						7.5KW							
15	3580	97.58	1.20	WFA 97 WFAF97 WF 97 WFF 97	4P	4.6	14300	312	0.85	WFA 127WR87 WFAF127WR87 WF 127WR87 WFF 127 WR87	4P		
16	3300	89.85	1.30			4.9	13500	293	0.90				
17	3180	86.59	1.35			5.5	11900	259	1.00				
18	2950	80.31	1.45			6.4	10300	223	1.15				
19	2780	75.63	1.55			7.2	9080	198	1.30				
20	2660	72.30	1.60										
22	2400	65.47	1.80			3.3	21600	217.62	0.85	WFA 157 WFAF157 WF 157 WFF 157	8P		
25	2130	58.06	2.0			4.0	17700	178.20	1.00				
27	1930	52.49	2.2			4.4	16200	162.96	1.10				
						5.1	14100	141.80	1.30				
16	3230	88.01	0.95	WFA 87 WFAF87 WF 87 WFF 87	4P	5.8	12400	125.14	1.45				
19	2810	76.39	1.05			6.6	10800	108.49	1.65				
21	2510	68.40	1.20			7.5	9600	96.53	1.85				
25	2080	56.75	1.45			8.4	8530	85.80	2.1				
28	1850	50.36	1.60			9.2	7810	78.46	2.3				
32	1660	45.28	1.70			11	6790	68.28	2.7				
36	1440	39.30	1.90			12	5990	60.25	3.0				
41	1290	35.19	2.0			14	5200	52.24	3.5				
49	1070	29.20	2.3			15	4620	46.48	3.9				
42	1250	33.92	2.1			18	3980	40.06	4.5				
50	1060	28.78	2.3										
54	970	26.50	3.1			3.6	20000	267.43	0.90	WFA 157 WFAF157 WF 157 WFF 157	6P		
60	870	23.68	3.5			4.4	16200	217.62	1.10				
						5.4	13300	178.20	1.35				
30	1780	48.37	0.85	WFA 77 WFAF77 WF 77 WFF 77	4P	5.9	12200	162.96	1.50				
33	1600	43.58	0.95			6.8	10600	141.80	1.70				
37	1400	38.23	1.05			7.7	9340	125.14	1.95				
42	1240	33.74	1.20			8.9	8090	108.49	2.2				
48	1100	29.91	1.35			9.9	7200	96.53	2.5				
56	940	25.54	1.55			11	6400	85.80	2.8				
56	940	25.50	1.60			12	5850	78.46	3.1				
67	785	21.43	1.90			14	5090	68.28	3.5				
73	725	19.70	2.1			16	4500	60.25	4.0				
82	645	17.49	2.3			18	3900	52.24	4.6				
91	575	15.64	2.6										
102	515	14.06	2.9			5.7	12500	125.04	0.95	WFA 127 WFAF127 WF 127 WFF 127	8P		
117	450	12.21	3.3			6.3	11400	114.04	1.05				
						7.3	9840	98.69	1.20				
						8.2	8690	87.08	1.40				
						5.6	12700	170.38	0.95	WFA 127 WFAF127 WF 127 WFF 127	6P		
65	810	22.05	1.00	WFA 67 WFAF67 WF 67 WFF 67	4P	6.2	11500	153.27	1.05				
68	770	20.90	1.05			7.7	9350	125.04	1.30				
78	670	18.29	1.20			8.4	8530	114.04	1.40				
87	605	16.48	1.35										
99	530	14.46	1.55			8.4	8530	114.04	1.40				
112	470	12.76	1.75										
126	415	11.31	1.95			8.4	8560	170.38	1.40	WFA 127 WFAF127 WF 127 WFF 127	4P		
148	355	9.66	2.3			9.3	7700	153.27	1.55				
158	335	9.08	1.60			11	6280	125.04	1.90				
166	315	8.60	1.80										
190	275	7.53	2.2			8.0	8950	178.64	0.85	WFA 107 WFAF107 WF 107 WFF 107	4P		
211	250	6.78	2.5			8.9	8080	161.28	0.95				
240	220	5.95	2.8			9.8	7340	146.49	1.05				
272	193	5.25	3.1			11	6410	129.97	1.20				
307	171	4.66	3.3			12	5910	117.94	1.30				
360	146	3.97	3.4			14	5080	101.38	1.50				
						15	4630	92.47	1.65				
85	620	16.81	0.95	WFA 57 WFAF57 WF 57 WFF 57	4P	16	4430	88.49	1.75				
90	585	15.88	1.05			17	4210	63.99	1.85				
106	495	13.52	1.20			19	3730	74.52	2.1				
116	450	12.29	1.35			21	3390	67.62	2.3				
134	390	10.64	1.55										
175	300	8.19	1.40			15	4890	97.58	0.90	WFA 97 WFAF97 WF 97 WFF 97	4P		
185	285	7.73	1.50			16	4500	89.85	0.95				
217	240	6.58	1.75			17	4340	86.59	1.00				
239	220	5.98	1.90			18	4020	80.31	1.05				
276	190	5.18	2.2			19	3790	75.63	1.15				
						20	3620	72.30	1.20				
						22	3280	65.47	1.30				

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
7.5KW						11.0KW							
25	2910	58.06	1.50	WFA 97 WFAF97 WF 97 WFF 97	4P	5.4	19500	267.43	0.90	WFA 157 WFAF157 WF 157 WFF 157	4P		
27	2630	52.49	1.65			6.6	15900	217.62	1.15				
32	2230	44.49	1.95			8.1	13000	178.20	1.40				
37	1950	38.86	2.2			8.8	11900	162.96	1.50				
44	1630	32.50	2.6			10	10300	141.80	1.75				
33	2170	43.28	1.40			12	9130	125.14	1.95				
39	1840	36.64	1.65			13	7910	108.49	2.3				
42	1700	33.91	2.5			15	7040	96.53	2.6				
47	1520	30.39	2.8			17	6260	85.80	2.9				
						18	5720	78.46	3.1				
						21	4980	68.28	3.6				
25	2840	56.75	1.05	WFA 87 WFAF87 WF 87 WFF 87	4P	7.7	13700	125.04	0.85	WFA 127 WFAF127 WF 127 WFF 127	6P		
28	2520	50.36	1.15			8.4	12500	114.04	0.95				
32	2270	45.28	1.25			9.7	10800	98.69	1.10				
36	1970	39.30	1.40			11	9550	87.08	1.25				
41	1760	35.19	1.50			13	8250	75.21	1.45				
49	1460	29.20	1.70			8.4	12500	170.38	0.95	WFA 127 WFAF127 WF 127 WFF 127	4P		
50	1440	28.78	1.70			9.4	11200	153.27	1.05				
54	1330	26.50	2.3			11	9150	125.04	1.30				
60	1190	23.68	2.5			13	8340	114.04	1.45				
67	1070	21.32	2.8			15	7220	98.69	1.65				
74	970	19.31	3.1			16	6370	87.08	1.90				
84	860	17.12	3.5			19	5500	75.21	2.2				
92	775	15.48	3.9										
42	1690	33.74	0.90	WFA 77 WFAF77 WF 77 WFF 77	4P	12	8600	117.94	0.90	WFA 107 WFAF107 WF 107 WFF 107	4P		
48	1500	29.91	1.00			14	7400	27.57	1.05				
56	1280	25.54	1.15			16	6750	25.14	1.15				
56	1280	25.50	1.15			17	6130	83.99	1.25				
67	1070	21.43	1.40			19	5440	74.52	1.40				
73	990	19.70	1.50			21	4930	67.62	1.55				
82	880	17.49	1.70			25	4240	58.12	1.80				
91	785	15.64	1.90			28	3700	50.73	2.1				
102	705	14.06	2.1			33	3140	43.03	2.5				
117	610	12.21	2.5			43	2470	33.79	3.0				
131	545	10.93	2.7			52	2010	27.57	3.9				
154	465	9.30	2.3			57	1830	25.14	4.3				
173	415	8.26	2.6										
194	370	7.38	2.9			22	4780	65.47	0.90	WFA 97 WFAF97 WF 97 WFF 97	4P		
215	335	6.64	3.2			25	4240	58.06	1.00				
248	290	5.76	3.7			27	3830	52.49	1.10				
277	260	5.16	4.2			32	3250	44.49	1.30				
344	215	4.28	4.7			37	2830	38.86	1.50				
11.0KW						44	2370	32.50	1.80				
4.8	20300	302	0.90	WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P	42	2470	33.91	1.75				
5.3	18300	273	1.00			47	2220	30.39	1.95				
6.2	15500	232	1.15			52	2000	27.44	2.2				
7.1	13500	202	1.35			58	1820	24.92	2.4				
7.3	13200	197	1.35			65	1610	22.11	2.7				
6.4	15000	223	0.80	WFA 127WR87 WFAF127WR87 WF 127WR87 WFF 127 WR87	4P	37	2870	39.30	0.95	WFA 87 WFAF87 WF 87 WFF 87	4P		
7.3	13300	198	0.90			41	2570	35.19	1.00				
8.7	11100	166	1.10			49	2130	29.20	1.20				
						54	1930	26.50	1.55				
5.1	20700	141.80	0.85	WFA 157 WFAF157 WF 157 WFF 157	8P	61	1730	23.68	1.75				
5.8	18300	125.14	1.00			68	1560	21.32	1.95				
6.6	15800	108.49	1.15			75	1410	19.31	2.1				
7.5	14100	96.53	1.30			84	1250	17.12	2.4				
						93	1130	15.48	2.7				
5.4	19500	178.20	0.90	WFA 157 WFAF157 WF 157 WFF 157	6P	110	960	13.12	3.1				
5.9	17800	162.96	1.00			73	1440	19.70	1.05	WFA 77 WFAF77 WF 77 WFF 77	4P		
6.8	15500	141.80	1.15			82	1280	17.49	1.20				
7.7	13700	125.14	1.30			92	1140	15.64	1.30				
8.9	11900	108.49	1.50			102	1030	14.06	1.45				
9.9	10600	96.53	1.70			118	890	12.21	1.70				
11	9390	85.80	1.90			132	795	10.93	1.90				
12	8590	78.46	2.1			155	680	9.30	1.60				

WF

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole		
11.0KW						15.0KW							
174	605	8.26	1.80	WFA 77 WFAF77 WF 77 WFF 77	4P	59	2450	24.92	1.75	WFA 97 WFAF97 WF 97 WFF 97	4P		
195	540	7.38	2.0			66	2170	22.11	2.0				
217	485	6.64	2.2			73	1970	20.07	2.2				
250	420	5.76	2.6			85	1690	17.25	2.5				
279	375	5.16	2.9			97	1480	15.06	2.9				
336	310	4.28	3.2			114	1250	12.77	3.4				
15KW						18.5KW							
6.3	20900	232	0.85	WFA 157WR97	4P	55	2600	26.50	1.15	WFA 87 WFAF87 WF 87 WFF 87	4P		
7.2	18300	202	1.00	WFAF157WR97		62	2320	23.68	1.30				
7.4	17700	197	1.00	WF 157WR97		68	2090	21.32	1.45				
				WFF 157 WR97		76	1890	19.31	1.60				
6.8	20900	141.80	0.85	WFA 157 WFAF157 WF 157 WFF 157	6P	85	1680	17.12	1.80				
7.8	18500	125.14	0.95			94	1520	15.48	2.0				
8.9	16000	108.49	1.10			111	1290	13.12	2.3				
10	14300	86.53	1.25			127	1120	11.46	2.7				
11	12700	85.80	1.40			152	940	9.58	3.1				
						176	810	8.30	1.90				
6.7	21400	217.62	0.85	WFA 157 WFAF157 WF 157 WFF 157	4P	199	720	7.35	2.1				
8.2	17500	178.20	1.05			220	650	6.65	2.3				
9.0	16000	162.96	1.15			259	555	5.63	2.8				
10	13900	141.80	1.30			297	485	4.92	3.2				
12	12300	125.14	1.45			355	405	4.12	3.6				
13	10600	108.49	1.70			18.5KW						WFA 157WR97 WFAF157WR97 WF 157WR97 WFF 157 WR97	4P
15	9470	96.53	1.90			7.2	22500	202	0.80				
17	8420	85.80	2.1			7.5	21800	197	0.80				
19	7700	78.46	2.3			WFA 157 WFAF157 WF 157 WFF 157	4P	8.2	21500	178.20	0.85	WFA 157 WFAF157 WF 157 WFF 157	4P
21	6700	68.28	2.7					9.0	19700	162.96	0.90		
24	5910	60.25	3.0	10	17100			141.80	1.05				
				12	15100			125.14	1.20				
				14	13100			108.49	1.40				
				15	11600			96.53	1.55				
9.8	14600	98.69	0.80	WFA 127 WFAF127 WF 127 WFF 127	6P	17	10300	85.80	1.75				
11	12900	87.08	0.95			19	9760	78.46	1.90				
13	11100	75.21	1.10			21	8230	68.28	2.2				
14	10300	69.89	1.15			24	7270	60.25	2.5				
15	9440	63.74	1.25			28	6300	52.24	2.9				
						13	13800	114.04	0.85	WFA 127 WFAF127 WF 127 WFF 127	4P		
12	12300	125.04	1.00	15	11900	98.69	1.00						
13	11200	114.04	1.05	17	10500	87.08	1.15						
15	9710	98.69	1.25	19	9090	75.21	1.30						
17	8570	87.08	1.40	21	8450	69.89	1.40						
19	7400	75.21	1.60	23	7710	63.74	1.55						
21	6870	69.89	1.75	26	6670	55.16	1.80						
				30	5880	48.67	2.0						
16	9070	92.47	0.85	WFA 107 WFAF107 WF 107 WFF 107	4P	20	8990	74.52	0.85	WFA 107 WFAF107 WF 107 WFF 107	4P		
17	8680	88.49	0.90			22	8150	67.62	0.95				
17	8240	83.99	0.95			25	7010	58.12	1.10				
20	7310	74.52	1.05			29	6120	50.73	1.25				
22	6630	67.62	1.15			34	5190	43.03	1.50				
25	5700	58.12	1.35			39	4540	37.61	1.70				
29	4980	50.73	1.55			46	3830	31.80	2.0				
34	4220	43.03	1.80			43	4070	33.79	1.80				
39	3690	37.61	2.1			53	3320	27.57	2.4				
46	3120	31.80	2.5			58	3030	25.14	2.6				
43	3320	33.79	2.2			67	2620	21.76	3.0				
53	2700	27.57	2.9			WFA 97 WFAF97 WF 97 WFF 97	4P	38	4690	38.86	0.90	WFA 97 WFAF97 WF 97 WFF 97	4P
58	2470	25.14	3.2					45	3920	32.50	1.10		
67	2130	21.76	3.7					53	3310	27.44	1.30		
				59	3010			24.92	1.45				
				66	2670			22.11	1.60				


输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole				
18.5KW						22KW									
73	2420	20.07	1.80	WFA 97 WFAF97 WF 97 WFF 97	4P	69	3060	21.32	1.00	WFA 87 WFAF87 WF 87 WFF 87	4P				
85	2080	17.25	2.1			76	2770	19.31	1.10						
97	1820	15.06	2.4			86	2460	17.12	1.20						
115	1540	12.77	2.8			95	2220	15.48	1.35						
131	1350	11.16	3.0			112	1880	13.12	1.60						
69	2570	21.32	1.15	WFA 87 WFAF87 WF 87 WFF 87	4P	128	1640	11.46	1.85						
76	2330	19.31	1.30			153	1370	9.58	2.1						
86	2060	17.12	1.45			177	1190	8.30	1.30						
95	1870	15.48	1.60			199	1050	7.35	1.45						
112	1580	13.12	1.90			220	950	6.65	1.60						
128	1380	11.46	2.2			260	810	5.63	1.90						
153	1160	9.58	2.5			298	705	4.92	2.2						
177	1000	8.30	1.55			356	590	4.12	2.5						
199	890	7.35	1.75			30KW						WFA 157 WFAF157 WF 157 WFF 157	4P		
220	800	6.65	1.90			14	21100	108.49	0.85						
260	680	5.63	2.2			15	18800	96.53	0.95						
298	595	4.92	2.6			17	16700	85.80	1.10						
356	495	4.12	2.9	19	15300	78.46	1.20								
				22	13300	68.28	1.35								
				24	11700	60.25	1.55								
				28	10200	52.24	1.75								
				32	9060	46.48	2.0								
				37	7810	40.06	2.3								
22KW						19	14700	75.21	0.80	WFA 127 WFAF127 WF 127 WFF 127	4P				
10	20900	96.53	0.85	WFA 157	21	13700	69.89	0.90							
11	18600	85.80	0.95	WFAF157	23	12500	63.74	0.95							
12	17000	78.46	1.05	WF 157	27	10800	55.16	1.10							
14	14800	68.28	1.20	WFF 157	30	9510	48.67	1.25							
10	20300	141.80	0.90	WFA 157 WFAF157 WF 157 WFF 157	4P	35	8210	42.04	1.45						
12	17900	125.14	1.00			39	7270	37.18	1.65						
14	15600	108.49	1.15			47	6110	31.25	1.95						
15	13800	96.53	1.30			58	4930	25.24	2.4						
17	12300	85.80	1.45			55	5240	26.79	1.60						
19	11300	78.46	1.60			60	4790	24.50	1.80						
21	9790	68.28	1.85			69	4170	21.32	2.9						
24	8640	60.25	2.1			78	3680	18.82	3.0						
28	7490	52.24	2.4												
32	6660	46.48	2.7												
37	5740	40.06	3.1												
45	4670	32.55	3.9												
15	14200	98.69	0.85	WFA 127 WFAF127 WF 127 WFF 127	4P	34	8390	43.03	0.90	WFA 107 WFAF107 WF 107 WFF 107	4P				
17	12500	87.08	0.95			39	7330	37.61	1.05						
19	10800	75.21	1.10			46	6200	31.80	1.25						
21	10000	69.89	1.20			53	5370	27.57	1.45						
23	9160	63.74	1.30			58	4900	25.14	1.60						
26	7930	55.16	1.50			68	4240	21.76	1.85						
30	7000	48.67	1.70			77	3740	19.20	2.1						
35	6040	42.04	2.0			89	3230	16.58	2.4						
25	8330	58.12	0.90	WFA 107 WFAF107 WF 107 WFF 107	4P	100	2860	14.67	2.7			WFA 97 WFAF97 WF 97 WFF 97	4P		
29	7280	50.73	1.05			119	2400	12.33	2.9						
34	6170	43.03	1.25			148	1940	9.96	3.3						
39	5390	37.61	1.40												
46	4560	31.80	1.70			66	4310	22.11	1.00						
43	4850	33.76	1.55			73	3910	20.07	1.10						
53	3950	27.57	2.0			85	3360	17.25	1.30						
58	3610	25.14	2.2			98	2930	15.06	1.45						
67	3120	21.76	2.5			115	2490	12.77	1.75						
76	2750	19.20	2.8			132	2180	11.16	1.96						
						162	1770	9.06	1.35						
						179	1600	8.22	1.45						
53	3940	27.44	1.10	WFA 97 WFAF97 WF 97 WFF 97	4P	208	1380	7.07	1.70						
59	3570	24.02	1.20			238	1200	6.17	1.85						
66	3170	22.11	1.35			281	1020	5.23	2.1						
73	2880	20.07	1.50			321	890	4.57	2.3						
85	2470	17.25	1.75												
97	2160	15.06	2.0												
115	1830	12.77	2.3												
131	1600	11.16	2.6												

WF



输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole	输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole				
37KW						45KW									
17	20600	85.80	0.85	WFA 157 WFAF157 WF 157 WFF 157	4P	53	8060	27.57	0.95	WFA 107 WFAF107 WF 107 WFF 107	4P				
19	18900	78.46	0.95			58	7350	25.14	1.05						
22	16400	68.28	1.10			68	6060	21.76	1.25						
24	14500	60.25	1.25			77	5610	19.20	1.40						
28	12600	52.24	1.45			89	4850	16.58	1.60						
32	11200	46.48	1.60			100	4290	14.67	1.80						
37	9630	40.06	1.85			119	3600	12.33	1.95						
45	7820	32.50	2.3			148	2910	9.96	2.2						
53	6630	27.60	2.7			152	2830	9.69	1.75						
						176	2450	8.37	1.95						
						199	2160	7.40	2.1						
						236	1820	6.22	2.5						
27						55KW									
30	13300	55.16	0.90	WFA 127 WFAF127 WF 127 WFF 127	4P	24	21500	60.25	0.85	WFA 157 WFAF157 WF 157 WFF 157	4P				
35	11700	48.67	1.00			28	18600	52.24	0.95						
39	10100	42.04	1.20			32	16500	46.48	1.10						
47	8960	37.18	1.35			37	14300	40.06	1.25						
58	6080	25.24	1.95			45	11600	32.55	1.55						
55	6460	26.79	1.30			53	9830	27.60	1.85						
60	5910	24.50	1.45			52	10200	28.60	1.65						
69	5140	21.32	2.3			58	9060	25.43	1.65						
78	4530	18.82	2.4			67	7890	22.16	2.3						
90	3930	16.31	2.8			75	7040	19.77	2.4						
101	3500	14.51	3.1			88	6000	16.85	3.0						
117	3010	12.51	3.3												
144	2450	10.16	3.9												
166	2130	8.62	3.3												
186	1890	7.88	3.2												
53						40									
58	6040	25.14	1.30			WFA 107 WFAF107 WF 107 WFF 107	4P	47	11200			31.25	1.10	WFA 127 WFAF127 WF 127 WFF 127	4P
68	5230	21.76	1.50					58	9010			25.24	1.35		
77	4610	19.20	1.70	69	7610			21.32	1.60						
89	3990	16.58	1.95	78	6720			18.82	1.65						
100	3530	14.67	2.2	90	5820			16.31	1.90						
119	2960	12.33	2.4	101	5180			14.51	2.1						
148	2390	9.96	2.7	118	4470			12.51	2.2						
152	2330	9.69	2.1	145	3630			10.16	2.6						
176	2010	8.37	2.4	166	3160			8.62	2.2						
199	1780	7.40	2.6	187	2810			7.88	2.1						
236	1500	6.22	3.1	217	2420			6.80	2.9						
								267	1970	5.52	3.0				
								315	1670	4.68	3.6				
45KW								75KW							
22	20000	68.28	0.90	WFA 157 WFAF157 WF 157 WFF 157	4P			32	22500	46.48	0.80	WFA 157 WFAF157 WF 157 WFF 157	4P		
24	17600	60.25	1.00			37	19400	40.06	0.95						
28	15300	52.24	1.20			45	15800	32.55	1.15						
32	13600	46.48	1.30			54	13400	27.60	1.35						
37	11700	40.06	1.55			52	13800	28.60	1.25						
45	9510	32.55	1.90			58	12300	25.43	1.20						
53	8070	27.60	2.2			67	10700	22.16	1.70						
						75	9570	19.77	1.80						
						88	8150	16.85	2.2						
						106	6760	13.96	2.5						
						124	5770	11.92	2.8						
30						58									
35	12300	42.04	0.95	WFA 127 WFAF127 WF 127 WFF 127	4P	69	10300	21.32	1.15	WFA 127 WFAF127 WF 127 WFF 127	4P				
39	10900	37.18	1.10			78	9130	18.82	1.20						
47	9160	31.25	1.30			90	7920	16.31	1.40						
58	7400	25.24	1.60			102	7040	14.51	1.55						
55	7850	26.79	1.10			118	6070	12.51	1.65						
60	7180	24.50	1.20			145	4930	10.16	1.95						
69	6250	21.32	1.90			167	4290	8.62	1.65						
78	5520	18.82	2.0			188	3810	7.88	1.55						
90	4780	16.31	2.3			218	3290	6.80	2.1						
101	4250	14.51	2.6			268	2670	5.52	2.2						
117	3670	12.51	2.7			316	2270	4.68	2.7						
144	2980	10.16	3.2												
166	2590	8.62	2.7												
186	2300	7.88	2.6												
216	1990	6.80	3.5												
266	1610	5.52	3.7												

输出转速 Output speed (r/min)	输出转矩 Output torque (N.M)	传动比 Ratio (i)	使用系数 Service factor (f _B)	机型号 Type	电机级数 Motor pole
90KW					
45	18900	32.55	0.95		4P
54	16000	27.60	1.10		
52	16600	28.60	1.00		
58	14800	25.43	1.00	WFA 157	
67	12900	22.16	1.40	WFAF157	
75	11500	19.77	1.50	WF 157	
88	9790	16.85	1.85	WFF 157	
106	8110	13.96	2.1		
124	6920	11.92	2.3		
58	14700	25.24	0.80		4P
69	12400	21.32	0.95		
78	11000	18.82	1.00		
90	9500	16.31	1.15		
102	8450	14.51	1.30	WFA 127	
118	7280	12.51	1.35	WFAF127	
145	5920	10.16	1.60	WF 127	
167	5150	8.62	1.35	WFF 127	
188	4580	7.88	1.30		
218	3950	6.80	1.75		
268	3210	5.52	1.85		
316	2720	4.68	2.2		
110KW					
54	19500	27.60	0.90		4P
67	15700	22.16	1.15	WFA 157	
75	14000	19.77	1.20	WFAF157	
88	11900	16.85	1.50	WF 157	
106	9880	13.96	1.70	WFF 157	
125	8430	11.92	1.90		
132KW					
67	18800	22.16	1.15	WFA 157	4P
75	16800	19.77	1.20	WFAF157	
88	14300	16.85	1.50	WF 157	
106	11900	13.96	1.70	WFF 157	
125	10100	11.92	1.90		
160KW					
88	17300	16.85	1.05	WFA 157	4P
106	14400	13.96	1.20	WFAF157	
125	12300	11.92	1.30	WF 157	
200KW					
88	21700	16.85	0.85	WFA 157	4P
106	18000	13.96	0.95	WFAF157	
125	15300	11.92	1.05	WF 157	



WF





WF37




WFA37





WFF37






WFAF37





WFAZ37




WF..37WR17





WF..S37





电机需方配或配特殊电机
时需加联接法兰 (见第119页)




WF47













WF..T47







WFA47




WFF47





WFAF47




WFAZ47




WF..47WR17




WF..S47




电机需方配或配特殊电机
时需加联接法兰 (见第119页)




WF57






WFA57







WF..T57








WFF57






WFAF57





WFAZ57



WF..57WR37





WF..S57





电机需方配或配特殊电机
时需加联接法兰 (见第119页)


WF67





WFA67





WF..T67





WFF67




WFAF67



WFAZ67





WF..67WR37





WF..S67



电机需方配或配特殊电机
时需加联接法兰（见第119页）





WF77





WFA77





WFF77





WFAF77




WFAZ77




WF..77WR37





电机需方配或配特殊电机
时需加联接法兰 (见第119页)





WF..S77




WF87






WFA87





WF..T87






WFF87




WFAF87





WFAZ87







电机需方配或配特殊电机
时需加联接法兰 (见第119页)




WF..87WR57





WF..S87




WF97





WFA97





WF..T97





WFF97





WFAF97





WFAZ97




WF..97WR57









电机需方配或配特殊电机
时需加联接法兰 (见第119页)




WF..S97







WF107




WF..T107





WFA107





WFF107





WFAF107





WFAZ107




WF..107WR77






WF..S107







电机需方配或配特殊电机
时需加联接法兰 (见第119页)



WF







WF127







WF..T127


WFA127





WFF127






WFAF127





WFAZ127




WF..127WR77(87)





WF..S127





电机需方配或配特殊电机
时需加联接法兰 (见第119页)




WF157












WF..T157






WFA157



WFF157





WFAF157





WFAZ157



WF..157WR97



WF..S157



电机需方配或配特殊电机
时需加联接法兰（见第119页）

